



- : not available on camera
 *1: not available on software
 *2: not test on software

For multi stream support:
 Yes: multi stream fix to 500kbps/100kbps
 Yes*: multi stream setting support

Device Name	Tested Firmware	Video Format	Video Ch	Max Resolution	Audio	I/O Ch	PTZ	On-Edge Motion	UPnP	Auto Pan	Multi Stream Support	Remarks
VIP-S3230	2.420.IB01.1 .R	H.264 MJPEG	1	1920x1080	-	-	-	*2	*2	-	Yes*	
Note:	1. Video parameter setting and rotate function may result in failure by Day/Night profile. (Camera Firmware issue) 2.Stream parameter setting may fail if the ranges of bitrate and framerate or resolution are not synchronized with the camera web. (Camera Firmware issue) 3.Server Bitrate Value may not sync with web interface. (Camera Firmware issue)											
VIP-S4200	2.420.IB01.1 .R	H.264 MJPEG	1	1920x1080	-	-	-	*2	*2	-	Yes*	
Note:	1. Video parameter setting and rotate function may result in failure by Day/Night profile. (Camera Firmware issue) 2.Stream parameter setting may fail if the ranges of bitrate and framerate or resolution are not synchronized with the camera web. (Camera Firmware issue) 3.Server Bitrate Value may not sync with web interface. (Camera Firmware issue)											
VIP-S4220	2.420.IB01.1 .R	H.264 MJPEG	1	1920x1080	-	-	-	*2	*2	-	Yes*	
Note:	1. Video parameter setting and rotate function may result in failure by Day/Night profile. (Camera Firmware issue) 2.Stream parameter setting may fail if the ranges of bitrate and framerate or resolution are not synchronized with the camera web. (Camera Firmware issue) 3.Server Bitrate Value may not sync with web interface. (Camera Firmware issue)											
VIP-S4020	2.420.IB01.1 .R	H.264 MJPEG	1	1920x1080	-	-	-	*2	*2	-	Yes*	
Note:	1. Video parameter setting and rotate function may result in failure by Day/Night profile. (Camera Firmware issue) 2.Stream parameter setting may fail if the ranges of bitrate and framerate or resolution are not synchronized with the camera web. (Camera Firmware issue) 3.Server Bitrate Value may not sync with web interface. (Camera Firmware issue)											
VIP-S4000	2.420.IB01.1 .T	H.264 MJPEG	1	1920x1080	-	-	-	*2	*2	-	Yes*	
Note:	1. Video parameter setting and rotate function may result in failure by Day/Night profile. (Camera Firmware issue) 2.Stream parameter setting may fail if the ranges of bitrate and framerate or resolution are not synchronized with the camera web. (Camera Firmware issue) 3.Server Bitrate Value may not sync with web interface. (Camera Firmware issue)											
VIP-S3020	2.420.IB01.1 .R	H.264 MJPEG	1	1920x1080	-	-	-	*2	*2	-	Yes*	
Note:	1. Video parameter setting and rotate function may result in failure by Day/Night profile. (Camera Firmware issue) 2.Stream parameter setting may fail if the ranges of bitrate and framerate or resolution are not synchronized with the camera web. (Camera Firmware issue) 3.Server Bitrate Value may not sync with web interface. (Camera Firmware issue)											